



180°











WARNING! Stored Energy Hazard:

The arm mechanism is under tension and will move up rapidly, on its own, as soon as attached equipment is removed . For this reason, **DO NOT** remove equipment unless the arm has been moved to the highest position! Failure to follow this instruction may result in serious personal injury and/or equipment damage!





ZG1

